

## PNEUMATIC CUTTING MACHINE

**特點 Features :**

1. 以壓縮空氣作為動力源，操作簡單。  
Using compressed air as a power source, the operation is simple.
2. 無油壓系統待機時產生的噪音，省電降耗。  
No noise generated by standby system, save electricity and reduce consumption.
3. 利用氣液增壓原理，達到動作速度快、高出力的狀態。  
By using the principle of gas liquid boosting, we can reach the state of fast action and high output.
4. 多功能，適合成型、沖孔、鉚合、裝配、切斷等  
Multi-function, suitable for forming, punching, riveting, assembly, cutting and so on.
5. 出力調整方便，只需調整氣壓，就可達到所需出力。  
The output is easy to adjust, and only by adjusting the pressure of air pressure can we achieve the required output.
6. 結構簡單，操作容易。  
The structure is simple and the operation is easy.
7. 四柱型半開放設計，左右均做護罩板封閉。  
Four column type semi open design, left and right cover plates are closed.

**技術參數 Technical Parameter :**

作動條件	液壓油	工作溫度	電 壓
Actuating mode	Hydraulic oil	Working temperature	Voltage
4-7 kg/cm <sup>2</sup> compressed air	VG68# Antiwear hydraulic oil	0 – 60 °C	220 V

氣缸耐壓	運行速度	機器尺寸	淨 重
Cylinder withstand pressure	Running speed	Machine size	N.W.
12 kg/cm <sup>2</sup>	30 ~100 times/min	750 x 600 x1700 mm	270 kg

控制方法：電控、氣控、手控、腳控

Control methods : Electronic control, gas control, hand control, foot control